# Dry Contact Interface for CIE-H10A/H14A (V1.2)

Customers can interface between CIE-H10A/H14A and dry contact sensors (switch, relays) by the following two methods.

- **Using Dry Contact Adapter(DCA)**
  - Customers can implement dry contact interfaces very easily with Dry Contact Adapter (DCA).
  - An Additional DC power is required for DCA.
  - Please refer to the https://www.eztcp.com for more information about DCA.

- **Implementing Dry Contact Interface**
  - Product's input ports senses DC voltage from sensors.
  - Above 4.5V: 1(on), Below 1.2V: 0(off)
  - Therefore, users have to implement as followed for Dry Contact Sensors.

- We recommend users to use a **DC 4.8V ~ 25V** power supply.
- We recommend users to use **isolated DC Power**.

Sollae Systems Co., Ltd.